

Oil Field Environmental Incident Summary

Incident: 20160822085554

Date/Time of Notice: 08/22/2016 08:55

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: BONNEY 2-3M

Field Name: JIM CREEK

Well File #: 18795

Date Incident: 8/20/2016

Time Incident: 12:00

Facility ID Number:

County: DUNN

Twp: 145

Rng: 96

Sec: 3

Qtr:

Location Description: Pasture adjacent to well site.

Submitted By: Patrick Skillestad

Received By:

Contact Person: Patrick Skillestad
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Gallons	3	Gallons	3	gallons

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/9/2016

Clean Up Concluded: 8/21/2016

Risk Evaluation:

None

Areal Extent:

20 ft x 30 ft

Potential Environmental Impacts:

Grass and topsoil in pasture.

Action Taken or Planned:

Landowner was contacted, misted grass was mowed and disposed of. NDIC On-Call inspector was notified of the release on Aug 21 at 7:36 am. The on-line report is outside of the 24 hour window due to website issues. The inspector was notified about the website issues and he said it was acceptable to submit the on-line report on the morning of Aug 22.

Wastes Disposal Location: Chimney Butte Disposal

Agencies Involved:

Updates

Date: 8/22/2016 **Status:** Reviewed - Follow-up Required

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spill was not contained; further follow-up is required.

Date: 8/31/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 8/31/2016, at 10:03 a.m. Area to the east off location has been mowed, approximately 100 X 30 ft. No remaining impacts to vegetation or soil noticed at this time. No further follow-up required.